


• OAO(MACH 3 BASS) SCHEMATIC DIAGRAM

LOCATION GUIDE	
C60	16
C51	15
C52	15
C53	15
C54	15
C55	15
C56	15
C57	15
C58	15
C59	15
C60	15
C61	15
C62	15
C63	15
C64	15
C65	15
C66	15
C67	15
P1450	17
P1450	10
R50	15
R51	15
R52	15
R53	15
R54	15
R55	15
R56	15
R57	15
R58	15



P : POWER SWING
 N : 220V ONLY
 T1 : TURNER BAND
 T2 : TURNER BAND
 N : 120V ONLY
 D1 : 12V BAND
 D2 : 12V BAND
 N : 12V
 D1 : 12V BAND
 N : 12V BAND
 AS : 12V BAND
 AR : 12V BAND
 G : 220V
 K : 12V
 M : 12V
 L : 12V
 J : 12V
 I : 12V
 H : 12V
 F : 12V
 E : 12V
 D : 12V
 C : 12V
 B : 12V
 A : 12V

D. SCHEMATIC Mach/BASS
 LF-4585/05930/M130
 04.07.28 3854R13325A

2-25

Q

P

N

M

L

J

I

H

G

F

E

D

C

B

A